

## Speed Chart

Buell Blast P3 7500 Redline  
By: 08Uly

Gearing		RPM										Stock		Extended	
Primary	1.600	1500	2000	2500	3000	3500	4000	4500	5000	5500	6000	6500	7000	7500	
1st	2.690	8.0	10.7	13.4	16.0	18.7	21.4	24.1	26.7	29.4	32.1	34.8	37.4	40.1	
2nd	1.850	11.7	15.5	19.4	23.3	27.2	31.1	35.0	38.9	42.8	46.6	50.5	54.4	58.3	
3rd	1.430	15.1	20.1	25.1	30.2	35.2	40.2	45.3	50.3	55.3	60.3	65.4	70.4	75.4	
4th	1.180	18.3	24.4	30.5	36.6	42.7	48.8	54.8	60.9	67.0	73.1	79.2	85.3	91.4	
5th	1.000	21.6	28.8	36.0	43.1	50.3	57.5	64.7	71.9	79.1	86.3	93.5	100.7	107.9	
Final	2.963														

M  
P  
H

### Owners manual recommended shift points

Upshift	MPH	RPM
1st to 2nd	15	2806
2nd to 3rd	25	3216
3rd to 4th	35	3480
4th to 5th	45	3692

Downshift	MPH	RPM
2nd to 1st	10	1286
3rd to 2nd	20	1989
4th to 3rd	30	2461
5th to 4th	40	2781

5th Gear										Stock		Extended	
MPH	50	55	60	65	70	75	80	85	90	93.5	100	107.9	
RPM	3477	3824	4172	4520	4867	5215	5562	5910	6258	6500	6953	7500	

1. Based on 72 inches of wheel travel (6 feet) with stock tire.